


Imagerie du béton : Comment l'approche multi-technologique facilite une inspection de classe mondiale



Proceq GP8000 results showing rebar and a large void (top right). The concrete was cored and the void was confirmed. It is an example of a consolidation void.

