


Imaging del calcestruzzo: Come l'approccio multi-tecnologico facilita l'ispezione di livello mondiale



Proceq GP8000 results showing rebar and a large void (top right). The concrete was cored and the void was confirmed. It is an example of a consolidation void.

