


Imagiologia do betão: Como a abordagem multi-tecnológica facilita a inspeção de classe mundial



Proceq GP8000 results showing rebar and a large void (top right). The concrete was cored and the void was confirmed. It is an example of a consolidation void.

